EN 18815

17 November 1958

MEMORANDUM FOR THE RECORD

SUBJECT: Aircraft Cargo Doors (ED-188A) and Dispatching Conveyor (ED-188B) for C-54 Aircraft

1. On 13 November the undersigned visited to discuss the status of prejects ED-188A and

- 2. The project engineer for informed the undersigned that 85% of all engineering drawings for the cargo doors (ED-188A) have been completed and released for fabrication. Approximately 30% of the door components are finished and are being held for final assembly. The balance of engineering to complete the door design (15%) is composed of the final assembly drawings and one or two minor airframe members.
- 3. The undersigned requested that the contractor allow for access covers in the cargo doors at the door mechanism locations for maintenance. A planning sketch (A/A #C-379-10) was obtained from the contractor which illustrates the door latching mechanisms. The majority of the latching mechanism components are cast to eliminate costly machining expenses. Standard parts (gears, shafting, etc.) have been incorporated in the design to aid in manufacture as well as maintenance procurement.
- 4. In the past month the contractor has engaged in an extensive effort to complete design and fabrication of the dispatching conveyor (ED-188B). At present 60% of all engineering drawings have been completed and released for manufacture. There is at this time, no finished components for the conveyor on hand. All necessary hardware (casters, roller bearings, etc.)
- 5. The "dry run" testing of the dispatching conveyor has been scheduled for the week of 8 December. The complete system will undergo simulated dispatching. The contractor has an area inside one of the shop buildings which will be used for the test set up. The end of the conveyor will terminate at a 4 foot drop height. Bundles of various sizes pallets, and lashings will be furnished by PFS/AD (Ref:

 | Dummer ballast | Dummer bal

CONFIDENTIAL

25X1

25X1

25X1

25X1 25X1

25X1

CONFIDENTIAL

6 Bonding the moults shipting and the Barry of the same	
6. Pending the results obtained from the "dry run" test of the dis-	•
patching conveyor, it may be desirable to redesign the exit and converging	*
portions of the system to accomplate the large portion of the cargo door.	>
Such a change may be contemplated by PPS/AD. If the decision is reached	
to redesign then a change in the scope of the program is necessary. The	
contractor feels that a redesign can be accomplated in the original	
allotted time, providing no major engineering problems arise.	
7. Installation of the cargo doors (and conveyor) is still schedule	ć
for the week of 12 January 1959. The site of institution remains to be	

for the week of li chosen. Original	2 January 1959. The site of	and conveyor) is still scheduled of instllation remains to be would provide an
space would be \$35	00 for one week with an ad	ditional \$1000.00 for special availability of hanger space
initial assembly i and technique. Po	ger space be obtained for s to be used to determine	the installation, since the "bugs" and installation procedure itside in inclement weather will
Aircraft Cargo Do	he undersign's visit, the fors) is over-running by ap- icating the door corner mo	contractor disclosed that Task I proximately \$4000.00 due to low lding strips.

25X1

25X1

25X1

25X1

estimation on fabricating	the door corner	approximately \$400 molding strips.	0.00 due to low
:mt			
cc:			

L. WINKL